

## LIBERO W Event Report

Event No	Type	Reason / Description	Date / Time
00048	Information	PDF created	21.Feb.2017 10:45:28
00047	Information	Mark set	21.Feb.2017 10:42:19
00046	Information	Mark set	21.Feb.2017 10:41:57
00045	Warning	Make PDF	21.Feb.2017 10:11:11
00044	Information	PDF created	14.Feb.2017 10:11:09
00043	Information	No sensor-connection	12.Feb.2017 01:39:56
00042	Information	No sensor-connection	12.Feb.2017 01:39:44
00041	Alarm acknowledge	Button pressed	10.Feb.2017 10:23:35
00040	Information	Mark set	10.Feb.2017 10:23:32
00039	Alarm	L1 below 15.0 °C	10.Feb.2017 10:23:17
00038	Information	No sensor-connection	10.Feb.2017 10:21:38
00037	Information	Mark set	10.Feb.2017 10:21:32
00036	Information	Mark set	10.Feb.2017 10:21:24
00035	Warning	L1 below 15.0 °C	10.Feb.2017 10:21:17
00034	Warning	H1 over 25.0 °C	10.Feb.2017 10:21:17
00033	Information	No sensor-connection	10.Feb.2017 10:20:56
00032	Information	No sensor-connection	10.Feb.2017 10:20:32
00031	Information	No sensor-connection	10.Feb.2017 10:19:50
00030	Information	No sensor-connection	10.Feb.2017 10:19:17
00029	Information	No sensor-connection	10.Feb.2017 10:14:53
00028	Information	Mark set	10.Feb.2017 10:02:14
00027	Information	Mark set	10.Feb.2017 10:02:08
00026	Alarm acknowledge	Button pressed	10.Feb.2017 10:01:57
00025	Information	Mark set	10.Feb.2017 10:01:53
00024	Information	Mark set	10.Feb.2017 10:01:38
00023	Information	No sensor-connection	09.Feb.2017 19:40:20
00022	Alarm	L1 below 15.0 °C	09.Feb.2017 19:40:17
00021	Alarm	H1 over 25.0 °C	09.Feb.2017 19:40:17
00020	Warning	L1 below 15.0 °C	09.Feb.2017 19:38:17
00019	Warning	H1 over 25.0 °C	09.Feb.2017 19:38:17
00018	Information	No sensor-connection	09.Feb.2017 19:38:08
00017	Information	No sensor-connection	09.Feb.2017 19:37:59
00016	Information	No sensor-connection	09.Feb.2017 19:37:41
00015	Information	No sensor-connection	09.Feb.2017 19:34:11
00014	Information	No sensor-connection	09.Feb.2017 19:33:59
00013	Information	No sensor-connection	09.Feb.2017 19:33:02
00012	Information	No sensor-connection	09.Feb.2017 19:32:35
00011	Information	No sensor-connection	09.Feb.2017 19:32:23
00010	Alarm acknowledge	Button pressed	07.Feb.2017 11:05:23
00009	Information	Mark set	07.Feb.2017 11:05:20
00008	Information	Mark set	07.Feb.2017 11:05:15
00007	Information	Mark set	07.Feb.2017 11:05:01
00006	Alarm	H1 over 25.0 °C	07.Feb.2017 11:04:17
00005	Warning	H1 over 25.0 °C	07.Feb.2017 11:02:17
00004	Information	Sensor pairing failed	06.Feb.2017 19:05:00
00003	Information	No sensor-connection	02.Feb.2017 10:28:24
00002	Information	Sensor paired 83000024	02.Feb.2017 10:28:24
00001	Information	System configuration done	01.Feb.2017 15:58:01